

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCSS job management (PQIS) are available. This information may not be transmitted to third parties.

Total warranty repair days (WRD): 4 Day(s)

Status	Repair Start	Repair End	Dealer	Mileage
 	17/08/2026	27/08/2026	6130010	942 km
 Campaign			Location:	Campaign complete: AMB53 Re-program power electronics
			Symptom:	9900 Recall campaign
 Campaign			Location:	Campaign complete: AMC11 Re-code airbag control unit
			Symptom:	9900 Recall campaign
 Campaign			Location:	Campaign complete: ANA41 Check routing of wire harness for rear seat-belt buckle and rework it if necessary
			Symptom:	9900 Recall campaign
 Campaign			Location:	Campaign complete: ANA51 Reworking wire harness for front seats
			Symptom:	9900 Recall campaign
 Campaign			Location:	Campaign complete: ARB01 Replacing brake hose the left and right front axle
			Symptom:	9900 Recall campaign
 Campaign			Location:	Campaign complete: ARB63 Checking HVB cell modules and re-programming BMCE software
			Symptom:	9900 Recall campaign
 Campaign			Location:	Campaign complete: WNF71 Replace bolted connection of universal joint to steering column
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WNJ81 Update to software network VR19.0.1.
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WPK05 Re-programming PSM control unit
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign not feasible: WRA6Z Replacing vehicle charging cable on Porsche Mobile Charger Connect
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WRW13 Re-program external communication control unit (OTA-FC)
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WSS62 Re-programming 12V battery sensor
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WSK61 Checking charging cable with NEMA power plug and if necessary re-submitting and updating charging electronics
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WMP58 Check pressure sensors and replace them if necessary
			Symptom:	6600 Workshop campaign
 Campaign			Location:	Campaign complete: WTL21 Replacing electric passenger compartment heater
			Symptom:	6600 Workshop campaign